

Oil Field Environmental Incident Summary

Incident: 20150903152621 **Date/Time of Notice:** 09/03/2015 15:26

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: RICKY FEDERAL 5602 43-35H

Field Name: BONETRAIL

Well File #: 22349

Date Incident: 9/3/2015 **Time Incident:** 09:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 102

Sec: 35

Qtr:

Location Description:

Submitted By: Luke Radke

Received By:

Contact Person: Luke Radke
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Equipment Failure

Release Contained in Dike No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels	21	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Replace Gaskets

Wastes Disposal Location: Fluid will be put into tanks on location, affected soil will go to IHD

Agencies Involved:

Updates

Date: 9/3/2015 **Status:** Reviewed; Followup Required **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, impacted areas off location. Followup is required.

Date: 9/11/2015 **Status:** Inspected **Author:** Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

No appearance of oil off well pad. Pooling is present to south of tanks of what is apparently stormwater, no sheen seen on this stormwater. Oil seen in containment area around tanks. Appears to be scraped/replaced dirt on west portion of well pad. No offsite release observed.